


PC-SPRINT

TOP SOLDER CONNECTIONS



SOLDER "FEED THROUGH" WIRES TOP & BOTTOM
IF DOUBLE SIDED BOARD

DUPLICATE TOP CONNECTIONS WITH 30 ga WIRE ON BOTTOM OF BOARD
IF SINGLE SIDED BOARD

© Douglas A. Severson 11/85

